



1. North Approach



2. South Approach



3. West Elevation



4. East Elevation





5. Deck General View



4. Sagging Compression Seal





5. Leaking Joint



6. Approach Slab Spalls and Delaminations





7. Beam Spalls



8. Drop-In Girder Misaligned



9. Pier Cracks



10. Abutment Cracks with Efflorescence

BR 3-150 N&S Photos





11. Elastomeric Bearing Splitting



12. Channel Slope Erosion